ComX Computers
Product Specification Sheet

ALL-CAM-JB-110

Miro Allbro Camera-Den - 110 mm Junction Box

Product Overview

Miro ALL-CAM-JB-110 Allbro Camera-Den - 110 mm Junction Box (Camera not included)





Specifications

Specifications:

© 2022 Respective owners and brand holders. This table has been carefully researched and generated by ComXpert International CC (http://www.comx.co.za), however, errors and omissions may occur. Only references to South Africa apply. All products are sourced in South Africa from the official suppliers and the warranty is that of the local supplier. E&OE. This table and our site's content may be used on condition that this notice and link remains intact and unaltered.

Specifications	
Product Code	ALL-CAM-JB-110
Material	DMC (Dough Moulding Compound)
Operating Temperature	-50 degrees C to + 200 degrees C
Glow Wire Capability / Flammability	960 degrees / UL94 V0
Expected UV Life (Direct Exposure)	25 years +
IP Level	IP66

Product Information Online

For the latest product information, availability and purchasing details, please visit the product page:

Product page:
https://www.comx-computers.co.za/ALL-CAM-JB-110-Miro-Allbro-Camera-Den-110-mm-Junction-Box-p-267207.php

Images and specifications are provided for reference and are subject to change without notice. E&OE.

Terms of Use: https://www.comx-computers.co.za/terms-of-use.php
Terms of Sale: https://www.comx-computers.co.za/terms-of-sale.php

PDF generated: 2026-11-10 01:08:18.

This PDF was generated automatically and may include content prepared or assisted by automated or AI-based systems. While reasonable care is taken to ensure accuracy, errors or omissions may occur.

For the most current and accurate product information, please refer to the product information available on our website. If any specification or other information differs from information published elsewhere, please confirm the details with us before relying on the information or making a purchasing decision.

If you identify an error or discrepancy, please report it to us so that we may investigate and correct it where necessary.