ComX Computers
Product Specification Sheet

ED-ES3205P

Edimax 5P 10/100Mbps Ethernet switch, desktop

Product Overview

Edimax 5P 10/100Mbps Ethernet switch, desktop



Specifications

Features:

- Complies with the IEEE 802.3 and IEEE 802.3u standards.
- Provides Store-and-Forward architecture , Full Wire Speed forwarding and filtering rates.
- Supports Auto-MDI/MDI-X, full/half duplex modes and auto-negotiation.
- Supports flow control and Non-blocking architecture.

Specifications:

- Hardware interface: 5 x RJ-45 Fast Ethernet LAN Ports, LED Indicators- Power, LNK/ACT for LAN, Power.
- Functions: Non-Blocking, Store-and-Forward architecture, Full wire speed filtering, Auto-MDI/MDI-X and auto learning, Auto-negotiation.
- Power adapter: DC 9V, 0.5A.
- Standard: IEEE802.3 and IEEE802.3u, IEEE802.3x.
- Humidity & temperature: 10-95% (Non-condensing), 0~45 Degree Celsius.
- Memory buffer: 384K bits.
- MAC Address: 2K.
- Dimension: 111 x 68 x 25 mm.
- Certifications: CE, FCC.

Product Information Online

For the latest product information, availability and purchasing details, please visit the product page:

Product page:
https://www.comx-computers.co.za/ED-ES3205P-Edimax-5P-10-100Mbps-Ethernet-switch-desktop-p-41353.php

Images and specifications are provided for reference and are subject to change without notice. E&OE.

Terms of Use: https://www.comx-computers.co.za/terms-of-use.php
Terms of Sale: https://www.comx-computers.co.za/terms-of-sale.php

PDF generated: 2026-11-11 03:25:22.

This PDF was generated automatically and may include content prepared or assisted by automated or AI-based systems. While reasonable care is taken to ensure accuracy, errors or omissions may occur.

For the most current and accurate product information, please refer to the product information available on our website. If any specification or other information differs from information published elsewhere, please confirm the details with us before relying on the information or making a purchasing decision.

If you identify an error or discrepancy, please report it to us so that we may investigate and correct it where necessary.