

NET-TL-WA1201

Tp-link TL-WA1201 Ac1200 Wireless Multifunction Access Point

Product Overview

Tp-link TL-WA1201 Ac1200 Wireless Multifunction Access Point



Specifications

Features:

- AC1200 Dual-Band Wi-Fi - 867 Mbps at 5 GHz and 300 Mbps at 2.4 GHz band.
- Flexible Deployment - Supports Passive PoE to carry electrical power and data simultaneously.
- Multiple Modes - Supports Access Point, Range Extender, Multi-SSID, and Client modes to meet any network needs.
- MU-MIMO Technology - Simultaneously transfers data to multiple devices for 2x faster performance.
- Boosted Coverage - Four fixed antennas equipped with Beamforming technology extend and concentrate the Wi-Fi signals.
- Captive Portal - Offers a designed portal page for heightened security and marketing.

Specifications:

© 2020 Respective owners and brand holders. This table has been carefully researched and generated by ComXpert International CC (<http://www.comx.co.za>), however, errors and omissions may occur. Only references to South Africa apply. All products are sourced in South Africa from the official suppliers and the warranty is that of the local supplier. E&OE. This table and our site's content may be used on condition that this notice and link remains intact and unaltered.

Specifications

Product Code	NET-TL-WA1201
HARDWARE FEATURES	
Interface	1x 10/100/1000 Mbps Ethernet Port (Supports Passive PoE)
Button	Power On/Off Button, WPS Button, Reset Button
External Power Supply	12V/1.5A
Wireless Standards	IEEE802.11b/g/n 2.4 GHz, IEEE 802.11ac/n/a 5 GHz
Dimensions (W x D x H)	225x145.5x37 in (400x255x72 mm)
Antenna Type	4 Fixed High Performance Antennas

WIRELESS FEATURES	
Frequency	2.4 GHz and 5 GHz
Signal Rate	867 Mbps at 5 GHz, 300 Mbps at 2.4 GHz
Reception Sensitivity	5 GHz:
	11a 6 Mbps: -95 dBm, 11a 54 Mbps: -81 dBm
	11ac VHT20(MCS0): -94 dBm, 11ac VHT20(MCS8): -71 dBm
	11n HT40(MCS0): -91 dBm, 11n HT40(MCS7): -71 dBm
	11ac VHT80(MCS0): -88 dBm, 11ac VHT80(MCS9): -63 dBm
	2.4 GHz:
	11g 54Mbps: -78 dBm
	11n HT20(MCS0): -92 dBm, 11n HT20(MCS7): -74 dBm
	11n HT40(MCS0): -88 dBm, 11n HT40(MCS7): -72 dBm
Transmit Power	CE:
	FCC:
Wireless Modes	Access Point, Range Extender, Client, Multi-SSID
Wireless Functions	Enable/Disable Wireless Radio, WDS Bridge, WMM, Wireless Statistics, Wireless Multicast Forwarding, DHCP Server, Access Control
Wireless Security	64/128-bit WEP, WPA/WPA2, WPA-PSK/WPA-PSK2 encryptions
DHCP	Server, DHCP Client List
Quality of Service	WMM
Advanced Functions	Captive Portal
OTHERS	
Certification	CE, FCC, RoHS
Package Contents	Wireless Access Point TL-WA1201
	Power Adapter
	RJ45 Ethernet Cable
	Quick Installation Guide
	PoE Power Injector
System Requirements	Microsoft Windows 98SE, NT, 2000, XP, Vista or Windows 7, 8, 8.1,
	10, MAC OS, NetWare, UNIX or Linux
	Internet Explorer 11, Firefox 12.0, Chrome 20.0, Safari 4.0, or other
	Java-enabled browser
Environment	Operating Temperature: 0 degreesC ~ 40 degreesC(32 degreesF ~ 104 degreesF)
	Storage Temperature: -40 degreesC ~ 70 degreesC (-40 degreesF ~ 158 degreesF)
	Operating Humidity: 10%~90% non-condensing
	Storage Humidity: 5%~90% non-condensing
Protocol Support	IPv4, IPv6

Product Information Online

For the latest product information, availability and purchasing details, please visit the product page:

Product page:

<https://www.comx-computers.co.za/NET-TL-WA1201-Tp-link-TL-WA1201-Ac1200-Wireless-Multifunction-Buy-p-242185.php>

Images and specifications are provided for reference and are subject to change without notice. E&OE.

Terms of Use: <https://www.comx-computers.co.za/terms-of-use.php>

Terms of Sale: <https://www.comx-computers.co.za/terms-of-sale.php>

PDF generated: 2026-10-16 12:13:10.

This PDF was generated automatically and may include content prepared or assisted by automated or AI-based systems. While reasonable care is taken to ensure accuracy, errors or omissions may occur.

For the most current and accurate product information, please refer to the product information available on our website. If any specification or other information differs from information published elsewhere, please confirm the details with us before relying on the information or making a purchasing decision.

If you identify an error or discrepancy, please report it to us so that we may investigate and correct it where necessary.