

RBC23

APC Replacement Battery Cartridge #23

Product Overview

APC Replacement Battery Cartridge #23, Shipping Weight: 24.00(lbs) 10.91(kilos), Shipping Dimensions: 6.00x 14.50x 19.50(in) 15.20x 36.80x 49.50(cent), UPC Code: 731304015789



Specifications

Specifications:

Batteries & Runtime	
Battery Volt-Amp-Hour Capacity	336
Battery Type	Maintenance-free sealed Lead-Acid battery with suspended electrolyte : leakproof
Battery mounting	Enclosed battery cartridge
Expected Battery Life (years)	3-5
RBC Quantity	1
Physical	
Net Weight	10.00 KG
Maximum Height	83.00 mm
Maximum Width	216.00 mm
Maximum Depth	343.00 mm
Shipping Weight	10.91 KG
Shipping Width	368.00 mm
Shipping Height	152.00 mm
Shipping Depth	495.00 mm
Color	Black
Units per Pallet	18
Environmental	

ComX Computers

Product Specification Sheet

Operating Environment	0 - 45 degreesC
Operating Relative Humidity	0 - 95%
Operating Elevation	0-3000 meters
Storage Temperature	-15 - 45 degreesC
Storage Relative Humidity	0 - 95%
Storage Elevation	0-15000 meters

Product Information Online

For the latest product information, availability and purchasing details, please visit the product page:

Product page: <https://www.comx-computers.co.za/RBC23-APC-Replacement-Battery-Cartridge-23-Buy-p-55913.php>

Images and specifications are provided for reference and are subject to change without notice. E&OE.

Terms of Use: <https://www.comx-computers.co.za/terms-of-use.php>

Terms of Sale: <https://www.comx-computers.co.za/terms-of-sale.php>

PDF generated: 2026-10-08 07:49:59.

This PDF was generated automatically and may include content prepared or assisted by automated or AI-based systems. While reasonable care is taken to ensure accuracy, errors or omissions may occur.

For the most current and accurate product information, please refer to the product information available on our website. If any specification or other information differs from information published elsewhere, please confirm the details with us before relying on the information or making a purchasing decision.

If you identify an error or discrepancy, please report it to us so that we may investigate and correct it where necessary.