

WH68 Hybrid

Charge Headset

The headset can be charged via a USB charging cable plugged directly into the headset.

USB Charging




TIP

- We recommend fully charging the headset when using it for the first time.
- It takes 1.5 hours to fully charge the headset.


LED Indicator

Charging



Breathing green LED indicator

Fully Charged



Green LED indicator